



2015 Torrance Refinery Explosion: Industry Impacts Then and Now

Melike Yersiz, Chemical Incident Investigator
U.S. Chemical Safety Board (CSB)

TU-A4

February 27, 2024



26th California Unified Program
Annual Training Conference
February 26-29, 2024



LIVE
AIR7 HD

BREAKING NEWS
REFINERY EXPLOSION
TORRANCE

11:01 69°



#ABC7Eyewitness

Agenda

- About the CSB
- Fluid Catalytic Cracking Overview
- Transient Operations
- 2015 Torrance, CA Incident

Break




- 2018 Superior, WI Incident
- Industry Response
- Hydrogen Fluoride Near-Misses
- California PSM Reform

About the CSB

- Independent federal agency
- The “Board” is a group of 5 individuals nominated by the President
- From 42 U.S. Code § 7412 (6)(C)(i):
 - “The Board shall investigate...determine and report to the public in writing...the cause or probable cause of any accidental release resulting in fatality, serious injury, or significant property damages.”
- Companies are required to report incidents to the CSB (40 C.F.R. Part 1604)


About the CSB

All completed investigation reports are available at www.csb.gov




26th California Unified Program
Annual Training Conference
February 26-29, 2024

Torrance Refinery Overview



City of Torrance
incorporated in 1921

Refinery constructed
in 1928-29




26th California Unified Program
Annual Training Conference
February 26-29, 2024



Torrance Refinery Overview


Refinery Proximity to Public Receptors:
Within a 3-mile radius of the refinery, there are:

- 330,000 people
- 71 schools
- 8 hospitals



January 4, 2016

- ✚ Digitized Point
- 🏥 Hospitals
- 🟡 Buffer Area
- 🏫 Schools







Sources: Esri, HERE, DeLorme, USGS, Intermap, Increment P Corp., NRCAN, Esri Japan, METI, Esri China (Hong Kong), Esri (Thailand), Mapbox, © OpenStreetMap contributors, and the GIS User Community

26th California Unified Program
Annual Training Conference
February 26-29, 2024

Fluid Catalytic Cracking (FCC) Overview


The FCC converts low-value, thick oil to higher value gasoline by “cracking” the large molecules apart into smaller molecules



Catalytic Cracking



Fluid Catalytic Cracking (FCC) Overview




FCC Units in Northern California (as of 1/1/23)

Chevron	Richmond
PBF	Martinez
Valero	Benicia

FCC Units in Southern California (as of 1/1/23)

Chevron	El Segundo
Phillips 66	Wilmington
Marathon	Carson
PBF	Torrance
Valero	Wilmington

Source: [EIA](#)




Source: [Canada Energy Regulator](#)

26th California Unified Program
Annual Training Conference
February 26-29, 2024



Fluid Catalytic Cracking (FCC) Overview




26th California Unified Program
Annual Training Conference
February 26-29, 2024

Fluid Catalytic Cracking (FCC) Overview



26th California Unified Program
Annual Training Conference
February 26-29, 2024



26th California Unified Program
 Annual Training Conference
 February 26-29, 2024

Transient Operations


Transient Operation:

The operating mode when the process is in transition and is not in its normal operations mode.

Examples:

Startup, shutdown, standby, emergency,
procedure-based operations


Transient Operations



During transient operation,
steam pressure separates the air and hydrocarbon
sides of the process

26th California Unified Program
Annual Training Conference
February 26-29, 2024

2015 Torrance, CA Incident



The image shows the cover of a CSB investigation report. At the top, there is a banner with the CSB logo and the text 'Investigation Report'. Below this, the title 'ExxonMobil Torrance Refinery' is prominently displayed, followed by 'Electrostatic Precipitator Explosion' and 'Torrance, California'. The incident date is listed as February 18, 2015, and the report number is No. 2015-02-I-CA. There are two photographs: one showing the refinery complex with smoke rising from a stack, and another showing a close-up of a damaged piece of equipment. A red box on the right side of the cover lists 'KEY ISSUES:' with four bullet points. At the bottom, it says 'Published May 2017' and 'CSB - ExxonMobil Torrance Refinery Investigation Report'.

CSB Investigation Report
U.S. Chemical Safety and Hazard Investigation Board

ExxonMobil Torrance Refinery
Electrostatic Precipitator Explosion
Torrance, California

Incident Date: February 18, 2015
On-Site Property Damage, Catalyst Particles Released to Community, Near Miss in MHF Alkylation Unit
No. 2015-02-I-CA

KEY ISSUES:

- Lack of Safe Operating Limits and Operating Procedure
- Safeguard Effectiveness
- Operating Equipment Beyond Safe Operating Life
- Re-use of Previous Procedure Variance Without Sufficient Hazard Analysis

Published May 2017 CSB - ExxonMobil Torrance Refinery Investigation Report

February 18, 2015

FCC unit was idled for unplanned maintenance

Pressure deviation allowed hydrocarbons to backflow in the process and ignite in the ESP

Consequences:

Four contractors sought first aid; no serious injuries/ fatalities
Catalyst dust dispersed into the community

[CSB report](#) / [YouTube video](#)

26th California Unified Program
Annual Training Conference
February 26-29, 2024



CSB

2015 Torrance, CA Incident

Safety Issues Identified by the CSB:

1. Safe Operating Limits: Lack of “safe park” procedure and verifiable operating parameters
2. Process Hazard Analysis: Reliance on 2012 variance without verifying safeguards
3. Mechanical Integrity
4. ESP Operation
5. Refinery management permitted opening process equipment without confirming to refinery standards

Industry Responses to Torrance Incident

- CSB investigation lessons shared widely across the refining industry
- YouTube video used as training tool
- Most refiners now automatically shut down the ESP during FCC unit transient operations
 - Process safety vs. Environmental impact
 - EPA updated [40 C.F.R. § 63.1564\(a\)\(5\)](#)

Deployment Activities



26th California Unified Program
Annual Training Conference
February 26-29, 2024

Stretch Break

(5 minutes)

2018 Superior, WI Incident



April 26, 2018

FCC unit was shutting down for a planned turnaround

Two vessels exploded around 10:00 a.m.

Explosion debris struck asphalt storage tank

Asphalt fire around 12:00 p.m.

Evacuation lifted at 6:00 a.m. the next morning

Consequences:

36 injuries (including 11 OSHA recordable injuries); no fatalities

39,000 pounds of flammable hydrocarbon vapor released

\$550 million property damage

[CSB report](#) / [YouTube video](#)


26th California Unified Program
Annual Training Conference
February 26-29, 2024



2018 Superior, WI Incident



Source: WDIO ABC
News




Source: Douglas County, Wisconsin

2018 Superior, WI Incident


Safety Issues Identified by the CSB:

1. Transient Operation Safeguards
2. Process Knowledge
3. Process Safety Management Systems
4. Industry Knowledge and Guidance
5. Brittle Fracture During Extreme Events
6. Emergency Preparedness

Torrance Refinery (2015)



Superior Refinery (2018)



26th California Unified Program
Annual Training Conference
February 26-29, 2024

2018 Superior, WI Incident

Refinery's FCC technology knowledge was not sufficient to safely shut down the FCC unit. As a result, refinery workers were not aware of explosion risk

CSB recommendations to Cenovus Energy:

- Develop an FCC PHA guidance document for use at all Cenovus-operated refineries
- Develop and implement a technology-specific knowledge-sharing network program across all Cenovus-operated refineries, which at a minimum includes an FCC technology peer network

2018 Superior, WI Incident

- Husky Superior Refinery knew about the Torrance incident, but workers did not recognize that inadvertent flow in the reverse direction was also possible
- Similar knowledge gaps may exist at other U.S. refineries
- Many different FCC unit designs exist through multiple technology licensors
- Currently, there is no industry publication that establishes common basic process safety expectations for all FCC units

Industry Response to Both FCC Incidents

- **2015: Torrance incident**
- **2017: CSB publishes Torrance report;** shared in conferences
- **2018: Superior incident; CSB publishes factual investigative update**
- **2019:** Refining industry survey on safe FCC operating practices
- **2020:** Webinar on safeguarding the FCC unit during transient operation
- **2020-2022:** AFPM publishes multiple webinars and practice sharing documents
- **2022: CSB publishes Superior report**
- **2023-2025:** FCC Process Safety Regional Workshops (“Safety Roadshow”)



Open CSB Recommendations for FCC Units

CSB Recommendation to API:

Develop a publicly available technical publication for the safe operation of FCC units

CSB Recommendation to EPA:

Develop a program that prioritizes and emphasizes inspections of FCC units in refineries that operate HF alkylation units

Hydrogen Fluoride (HF) Near-Misses

- HF acid is a toxic chemical and poses a severe hazard to the population and environment when a release occurs
- Causes severe damage to skin, respiratory system, and bones after exposure and can lead to death (30 ppm)
- Large release could impact hundreds of thousands of residents
- Torrance Refinery used Modified HF (MHF)
- **No HF was released in the Torrance and Superior incidents**





HF Near-Miss: Torrance

- Two MHF tanks approximately 80 feet south of the ESP
- Temporary scaffolding around tanks at time of incident
- Outside of ExxonMobil's minimum equipment spacing requirement



HF Near-Miss: Torrance



26th California Unified Program
Annual Training Conference
February 26-29, 2024

HF Near-Miss: Torrance

Another nearby vessel hit by explosion debris (not MHF)



26th California Unified Program
Annual Training Conference
February 26-29, 2024

HF Near-Miss: Torrance



Perimeter laser detection system compromised


26th California Unified Program
Annual Training Conference
February 26-29, 2024

HF Near-Miss: Superior



HF tank was 50 feet closer to the explosion than the punctured asphalt tank
(HF tank was not compromised)

26th California Unified Program
Annual Training Conference
February 26-29, 2024



Explosion Site

Crude Unit

FCC and Alky Units

Tank 101

Asphalt Spill

HF Near-Miss: Superior

- Post-incident, Superior Refinery implemented additional HF mitigation, including:
 - Rapid acid transfer system
 - Enhancements to existing water mitigation system
 - Additions and modifications of other safety features
- Providing assistance to the Douglas County Emergency Management Department on its emergency community alert system and community evacuation plan, including interactive drills

Source: [Cenovus](#)

Philadelphia Energy Solutions (PES)



June 21, 2019

Piping in HF alkylation unit ruptured
Vapor cloud ignited, fire led to other explosions

HF response:

- Approximately 5,000 lbs of HF released (no off-site impacts reported due to HF release)
- Rapid acid de-inventory: 339,000 lbs of HF drained
- Explosion compromised control system to remotely operate the water spray HF mitigation system

[CSB report](#) / [YouTube video](#)

26th California Unified Program
Annual Training Conference
February 26-29, 2024

Philadelphia Energy Solutions (PES)

“[A]ctive” safeguards—or safeguards that require a person or technology to trigger their activation—have the potential to fail in major incidents involving fire or explosions.

Refiners operating HF alkylation units need to improve the availability and reliability of active safeguards during incidents involving fire and explosions.

From CSB report: *Fire and Explosions at Philadelphia Energy Solutions Refinery Hydrofluoric Acid Alkylation Unit* (October 2022)

Open CSB Recommendations for HF

- **To EPA:** “Develop a program that prioritizes and emphasizes inspections of refinery HF alkylation units” and “FCC units in refineries that operate HF alkylation units”
- **To API:** “Update API RP 751 *Safe Operation of Hydrofluoric Acid Alkylation Units*”
- **To EPA:** “Revise 40 C.F.R. Part 68 (EPA Risk Management Plan) to require new and existing petroleum refineries with HF alkylation units to conduct a safer technology and alternatives analysis (STAA) and to evaluate the practicability of any inherently safer technology (IST) identified”
- **To EPA:** Initiate prioritization and, as applicable, risk evaluation of HF under the Toxic Substances Control Act

California PSM Reform

- California updated its PSM regulation for petroleum refineries ([Section 5189.1](#)) in 2017 in response to previous regulatory gaps the CSB identified:
 - [Chevron Refinery Fire](#) (2012)
 - [Tesoro Anacortes Refinery Fatal Explosion and Fire](#) (2010)
- Intended to make California petroleum refineries safer, including:
 - Hierarchy of Hazard Controls Analysis
 - Process Hazard Analysis that documents the effectiveness of safeguards
 - Damage Mechanism Review
 - Employee Participation, Human Factors, Process Safety Culture Assessment, and others



Open Discussion

Melike Yersiz, Chemical Incident Investigator, CSB

Melike.Yersiz@csb.gov

(202) 713-6702

www.csb.gov



26th California Unified Program
Annual Training Conference

February 26-29, 2024

