

COMPLETION AND UPA EVALUATION OF DESIGNATED OPERATOR INSPECTIONS February 9, 2021



23rd California Unified Program Annual Training Conference February 2 – March 18, 2021

Conducting Designated Operator Inspections



Preparing for Inspection



Conducting the inspection



Completing Inspection Form



CERS & Binder Review



Preparing for DO Inspection



Obtain Alarm History



UST – Alarm Log & Response

Date	Time	TYPE OF ALARM	Date	Time	TYPE OF RESPONSE	Initials



UST Compliance Binder

UST Compliance Binder

1	PERMIT TO OPERATE			
2	FINANCIAL CERTIFICATION			
3	CERS DOCUMENTATION			
4	DESIGNATED OPERATOR NOTIFICATION FORM & STATEMENT OF COMPLIANCE			
5	DESIGNATED OPERATOR ANNUAL TRAINING DOCUMENTATION			
6	MONTHLY DESIGNATED OPERATOR REPORTS			
7	MONITOR CERTIFICATION TEST REPORTS & OVERFILL TEST REPORTS			
8	SECONDARY (SB989) TEST RESULTS			
9	HMBEP (CERS) DOCUMENTATION			
10	HAZARDOUS WASTE MANIFESTS & EPA ID EVQ SURVEY SUBMITTALS			



Obtain Alarm History

CALIFORNIA





Get Ready to Inspect – Safety First!



Conducting DO Inspection; Spill Container

- If cones are available, set up around Spill Container
- Remove Spill Container cover
- Observe each Spill Container for liquid and/or debris
- Observe each for any damage
- Remove fill tube cap and observe for cracked or missing gasket
- Cap should fit tight
- Observe drop tube for any obstruction



Fill vs. Vapor Spill Container









Inspection: Under Dispenser Containment

- Secure with cones or vehicle in front of each dispenser.
- Open one side of dispenser
- Observe UDC for liquid, debris and/or damage
- Verify that sensor is properly placed at lowest spot & secured upright
- Sensors in sleeves should be verified that the are on the bottom of UDC
- If dispensers are larger than the UDC, diverters should be verified.



UDC Inspection





Sensor Check











- Additional items I check for customers upon request:
 - Hoses in good shape
 - Dispensers running when not in use.
 - AQMD requirements



New Designated Operator Form – as of October 1, 2020.

Page 1

- Section 1- Facility information Site location, CERS ID, Date
- Section 2 DO information & ICC Certification
- Section 3 Compliance issues
- Section 4 DO Certification



Appendix XIII
Underground Storage Tank
Designated UST Operator Visual Inspection Report

CERS ID 101000	Inspection Date 2/01/	/2021		
Facility Name Puepke's 66 Service				
Facility Address 1234 Avenida Paseo	City Rancho Santa Marg	ZIP Code 92688		
2. DESIGNATED UST OPERATOR INFORMA	ATION			
Name of Designated UST Operator Brenda Puepke	Phone (949) 529-4245	9		
ICC Certification 5248274	Certification Expirate 8/1/2022	Certification Expiration Date 8/1/2022		
3. COMPLIANCE ISSUES				

4. CERTIFICATION BY DESIGNATED UST OPERATOR CONDUCTING INSPECTION

I hereby certify that the visual inspection was performed in compliance with California Code of Regulations, title 23, division 3, chapter 16, section 2716 and all information provided herein is accurate.

Designated UST Operator Signature

Date Inspection Report Provided to Owner

2/1/202

CERS = California Environmental Reporting System, ICC = International Code Council, ID = Identification, NA = Not Applicable, UDC = Under-Dispenser Containment, UST = Underground Storage Tank



Page 2

- Section 5 Owner/Operator Description of Follow-up action
- Section 6 Owner/Operator Acknowledgment of Inspection Results
- Section 7 Inspection History
- Section 8 Release Detection Alarm History



service technician?

Underground Storage Tank
Designated UST Operator Visual Inspection Report

5. OWNER/OPERATOR DESCRIPTION OF FOLLOW-UP ACTION

Number the follow up actions to correspond to appropriate compliance issues from Section 3. 1. Liquid and debris removed by site employee during inspection. Liquid placed in liquid waste drum which is properly labeled. 6. OWNER / OPERATOR ACKNOWLEDGEMENT OF INSPECTION RESULTS I have reviewed the results of the designated UST operator inspection report and provided a description of the action(s) taken or to be taken to correct any compliance issues discovered. Name of UST Owner / Operator (print) Rocky Jones UST Owner/Operator Signature Date Signed 2/1/202 - manager 7. INSPÉCTION HISTORY Has each follow-up action of Section 3 from the previous Designated UST NA Yes No Operator Inspection Report been completed appropriately? \boxtimes (Attach documentation verifying appropriate service to this report.) 8. RELEASE DETECTION ALARM HISTORY Attach a copy of the alarm history report/log to this report. Yes No NA Is the monitoring system powered on and in proper operating mode? \boxtimes Has each alarm since the previous inspection been responded to appropriately? \boxtimes \bowtie (Attach documentation verifying appropriate service to this report.) Have all containment sumps, that have had an alarm since the previous



All answers marked "No" must be described by the designated UST operator in Section 3.

designated UST operator inspection report, been responded to by a qualified

Dogo 2 of 4

 \bowtie

Page 3

- Section 9
 - Containment sump release information
 - Spill container ID
 - UDC and/or transition containment





Underground Storage Tank Designated UST Operator Visual Inspection Report

9. UST SYSTEM INSPECTION					
List below and in Section 3 all contain	nment	sum	ps that have had a release detection	alarm	
since the previous Designated UST (perat	or Ins	spection Report and have not been re	spond	ded
			nt sumps listed below require a visua		
			s substance, and proper sensor locat	ion.	
Is the containment sump free of dama	· /		,		
Containment Sump ID	Yes	No	Containment Sump ID	Yes	No
Are all sensors in visually inspected con	ntainm	ent s	sumps located to detect a release at		
the earliest opportunity?					
			bris, and hazardous substances? Is the	fill pip	е
free of obstructions? Is fill cap securely			•		
Spill Containment ID	Yes	No	Spill Containment ID	Yes	No
87 Unleaded	\boxtimes				
91 Unleaded		×			
		haza	ardous substances and all sensors locate	ed to	
detect a release at the earliest opportur	ity?		o UDC(s) at this facility		
UDC ID	Yes	No	UDC ID	Yes	No
1/2 UDC					
3/4 UDC	×				
5/6 UDC	×				
7/8 UDC	\boxtimes				
Vent Transition Sump					
Vapor Pot Sump	×				
Mechanical float mechanisms used	in UD0	Cs.			

All answers marked "No" must be described by the designated UST operator in Section 3.

Page 4

Section 10 – Testing & Maintenance

Section 11 – Facility Employee Training

Section 12 – Comments



Underground Storage Tank Designated UST Operator Visual Inspection Report

10. TESTING AND MAINTENANCE	Yes	No	NA	Date last performed		
Has monitoring system certification been completed within the past 12 months?	×			12/1/2020		
Has spill container testing been completed within the past 12 months?				12/1/2020		
Has overfill prevention equipment inspection been completed within the past 36 months?				5/14/6019		
Has secondary containment testing been completed within the past 36 months?				11/13/18		
Has tank tightness testing been completed within required timeframes?						
Has line tightness testing been completed within the required timeframes?						
Other Test / Maintenance:	\boxtimes					
Other Test / Maintenance:	\boxtimes					
Other Test / Maintenance:	\boxtimes					
11. FACILITY EMPLOYEE TRAINING						
Have all individuals performing facility employee duties received the required facility						
employee training within the past 12 months?						
This section may be used to record comments or observations that are in deficiencies. Last DO Training - 11/21/2020 Overfill Prevention testing due by October 2021.	not cui	rrent c	compli	ance		



All answers marked "No" must be described by the designated UST operator in Section 3.

- Review Compliance binder for any outstanding issues.
- Discuss any outstanding items with Manager or Owner
- Get signature on page 2 of the DO Report
- Place in Compliance Binder on site



DO Training

- Provide training annually to designated employees
- Designated employees are to be trained prior to taking on the required duties.
- Physical walk-thru of facility.
- Review of compliance binder
- Discussion of employee's duties.



CER Review and Compliance Binder

- If requested by owner, review CERS information.
- Maintain current information in CERS
- Maintain site compliance binder for USTs, Hazardous Materials, Hazardous Wastes, APSA and AQMD Information.
- Binder example Index



Regulator Review of DO Program



UST D.O. Program Requirements

UST Designated Operator Program Requirements are found in 23 CCR 2715-2716.

This presentation demonstrates how one UPA reviews and evaluates while onsite.

Thank you for joining us!



Why a UST Designated Operator?

• California requires it in 2715.



Where can we tell who this is?

- CERS!
- CERS shall have a UST DO Statement that lists the name of the ICC Certified California UST Designated Operator (yes, it must be a <u>California ICC-certified professional</u>).



Pre-inspection CERS Review

Jot down who the listed UST DO is.

Good time to look up the UST DO license to see that it is current and active.

What if it has lapsed in 2020?



All ICC Certifications can be looked up online – By number:

https://www.iccsafe.org/verify/



Verify Professional Information

Enter your Candidate ID/ICC Record Number or your Email Address to see your on-file public record.

Search by Candidate ID or ICC Record Number



Or by Name

https://www.iccsafe.org/search-for-certified-

professionals/

First Name:	Global Services
City:	State:
	California
Certification Type:	
California UST System Operator (Designated)	Search Reset



CERS Pre-Inspection

Document all of the test dates based upon your file review.

- Make note of things like VPH, Single-walled, Double-walled system, suction, positive shut down, etc.
- SB989, Annual M/C date, spill container and Overfill Inspection dates.
- Did they all pass? Anything outstanding?

Anything you identify as outstanding should have also been identified in the monthly D.O. inspection.



Now you are onsite!

What I normally do:

After initial inspection duties, I will identify a good document review time.

Normally, that is the point when the tech is setting up for LLD

testing.



- Glasses
- Mask under the Gaiter
- Gloves
- Safe Distancing!





Document Review — 2020 style

Normally, I enter the station or office to review records.

These days, I request that the inspection records be brought outside so that I can limit time indoors.

I ask for this first as I am checking in with the station personnel for permission to inspect.



Basics of Document Review

Monthly Designated Operator inspection shall reflect onsite conditions when they inspected.

Each report shall have alarm history for the date of inspection. The date is printed either at top or bottom and should never be cut off/removed.

No alarm history? - Discuss



Inspection Report Format

Must use SWRCB inspection report as it is in the appendix of 23CCR Chapter 16.

Cannot be altered/changed, shrunken, redacted, etc... you get the idea!



Scenarios for discussion

- ELD Test Results? Where should they be?
 - Accessible and available for inspection.
- What if it has been more than xx years?
- Single-walled systems? How are they identifying that?
- The UST DO should be evaluating each site independently for compliance.
- Who is responsible if the UST DO is not properly documenting or completing the report?
- UST Owner/Operator is responsible.





Any Questions?

Brenda Puepke
Puepke Consulting
brenda@puepkeconsulting.com



Angie Samayoa Long Beach CUPA

Angela. Samayoa @longbeach.gov